

3.

MOTORCORP WEST

4935 MERCURY STREET
SAN DIEGO, CALIFORNIA 92111
TEL.: (714) 565-1414

To:

Husqvarna Dealers

From:

Claes Nilson, Service Department

Subject:

PORT TIMING MODIFICATION FOR 450cc ENGINE

Any modification done to a Husqvarna engine to increase power also increases the possibility of engine failures. Husqvarna will not accept any warranty claims on modified engines.

- (1) Cut out portion of cylinder liner down to aluminum base of cylinder.
- (2) Raise the corner of exhaust port, but keep the same height. Give the top corners a lmm radius.
- (3) Lower intake for 2mm. Raise the third transfer port to the same height as the other transfer port.
- (4) Shorten header pipe 30mm.

 Take out 15mm on each side and weld back on.







