





## The King of Open-Class Enduros—but only after some fiddling


ometimes, the best forward progress is made by going in the opposite direction. And Husqvarna's newest enduro bike, the 400WR, is a perfect example, for it has achieved some much-needed performance improvements through a design change that seems like a step backward. Because even though this new Husky belongs in the Open class of enduro competition, where the current trend is toward bigger and bigger engines, it has a *smaller* engine. Yet it's all the better for it.

Not that Husky's previous Open enduro, the 430WR, was such a terrible motorcycle. In many parts of the country, the 430 has been the predominant choice of Open-class enduro riders, with an impressive record of wins and championships to back up its popularity. But despite that, time had started to catch up with the 430. Its old-world brand of heavy-flywheeled, slow-revving power and slow-but-stable steering was gradually falling out of favor with today's breed of fast, young riders. A change was in order, and a pretty big one, at that.

For Husqvarna, that change is extensive indeed—although for most Japanese companies, the difference between last year's 430WR and this years's 400WR would be considered only minimal. But, in keeping with Husqvarna practice, the 400WR is comprised of only enough all-new hardware to get the job done, with the remainder consisting of tried-and-proven components. That technique keeps R&D and manufacturing costs down, and reliability up.

So the 400's engine is, basically, the 430WR bottom-end with an all new, liquid-cooled top-end. The stroke thus remains the same at 74mm, but the bore is smaller, down to 82.5mm from 86mm on the 430. That configuration yields 396cc and, according to Husqvarna spokesmen, precisely the kind of power they were looking for. Many displacements were tried in addition to 400 and 430cc, including 450cc and 488cc versions. But the desired power was achieved with the 400, and the liquid cooling was incorporated to insure that the engine would deliver that kind and level of power under all enduro-riding circumstances.

We didn't ride any of those larger-displacement prototypes, but after a month on the 400WR, we'll take Husqvarna's word for all of its claims. Because the engine is fantastic. It makes the 400WR considerably faster than the 430WR, and yet it's wonderfully tractable at low rpm. Usable power starts just above>






idle and builds smoothly and cleanly to about 3000 or 3500 rpm; and at that point, a second powerband kicks in and sends the 400 rocketing off in a rush, winding out like a factory-ported 250cc motocrosser. The transition between the lower and upper powerbands is fairly smooth if the throttle is only partially open or if the twistgrip is *rolled* open rather than being dumped wide-open. If you do the latter, as our testers soon found, the quick-revving motor leaps into its higher-rpm powerband with a vengeance, often with the front wheel airborne and the rider hanging on for dear life. After a few of those on a tight trail, you soon learn to be more gentle with the throttle.

Once the rider adapts to that transition, the dual powerbands prove very useful in a variety of trail conditions. The lower revs allow the 400 to torque through mud, over tree roots, around slippery off-camber turns and through tight corners about as tractably as the 430WR would. But when the woods open up and there's room for some good, old-fashioned acceleration, the high-rpm powerband lets the 400 roost down the trail at least as quickly as something with a full 500cc of displacement. And at any rpm, the engine responds crisply and immediately, which lets the rider loft the front wheel over any reasonable trail obstacle just by snapping the throttle open a little further.

A possible benefit of the 400WR's smaller displacement that engine vibration isn't as severe as it is on the 430WR especially on the 500WR, a limited-production, 488cc end model introduced early in 1984 as an alternative for powerazed woods riders). The 400's vibration generally is a higher frequency than the 430's, but is not as strong; and lower revs, the 400 is quite a lot smoother. Of course, the generally revs higher at any given trail speed than its 42 counterpart did, due to having less displacement and lot (higher numerically) primary and final-drive gearing; but of all, the new Husky vibrates less than any Open-class end bike we've ever tested.

It also ought to run cooler, what with it being the indust first liquid-cooled Open-class enduro bike. A crankshaft-dr water pump circulates coolant through the cylinder and hinto dual radiators mounted behind the single front fr downtube. That radiator location caused a problem in the ring of the exhaust system, though, by forcing the fattest parthe pipe to be far to the rear and in an area where it can in fere with the rider's left leg. The side numberplate protects rider from most of the heat; but the panel does not conf closely to the pipe's bends, so it makes the bike extremely very side of the side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely very side of the pipe's bends, so it makes the bike extremely side of the pipe's bends, so it makes the bike extremely side of the pipe's bends, so it makes the bike extremely side of the pipe's bends, so it makes the bike extremely side of the pipe's bends, so it makes the bike extremely side of the pipe's bends, so it makes



ne area just above the footpegs—so much so that the only to stand on the footpegs is to assume a bow-legged stance, sliding forward on the seat for a sharp righthand turn less the rider's left knee to contact the unshielded area of the , which can heat that part of his leg to the point of being ful.

local Husky dealer has come up with a simple fix for this slem. He removes the numberplate's front mounting screw spacer, then uses two plastic ties to secure the plate—one ip front to pull the plate in against the pipe, another under eft side of the seat to pull the plate in against the frame. The de of the plate is lined with a high-temperature rubber mateso it won't melt when drawn in against the pipe; and aligh the 400WR still will be fat enough in the midsection to the a slight cowboy-like stand-up riding position, the immement is worthwhile.

p, too, is it worth a 400WR owner's time and trouble to rove the front suspension action. As delivered, the Huskyt front fork is too harsh, and so it jolts the rider's hands and arms on big or abrupt bumps. We changed fork oil on our bike, swapping the stock 15-weight for lighter 10-weight still using the recommended volume of 15 ounces); we also


popped the fork seals loose, coated their lipped areas with oil to help the tubes slide through them more easily, then reinstalled them. After that, the fork worked nicely. It was exceptionally compliant and able to soak up all sorts of trail bumps, from the small chops to the biggest whoops and jump landings.

A similar sort of damping problem exists at the rear of the 400WR, but the remedy for this one is not so simple—or inexpensive. According to Husqvarna's tech people, "some" 400WRs (they couldn't say which ones or how many) are delivered with too much damping in their dual Ohlins rear shocks. The bikes that have this problem aren't hard to identify when ridden; they'll buck and hop and pound in a manner uncharacteristic of recent Husqvarnas. The company has issued a service bulletin that outlines a cure for this condition, but a private citizen probably won't be able to do the work himself, since it involves the use of special tools and some knowledge of how a shock works. Our test bike was one of the affected units, so we took the shocks to a Husky dealer who, for \$50 in labor and \$12 in parts, reworked them according to the bulletin.

Once that damping problem was cleared up, the 400WR's rear end behaved admirably. The shocks were then able to gobble up just about every kind of bump we could run under the>

rear wheel. The rear end seldom bottomed, and it never allowed the back of the bike to kick, either sideways or up and down.


As soon as we got the suspension sorted out, we were able to confirm Husqvarna's claims that the 400WR is not a typical Husky in the way it steers and handles. The bike is impressively quick and responsive through the tightest of trail-riding conditions—and not just quick for a Husky; it's quick compared to just about any full-size dirt bike there is. Some of that is due to the engine being so quick and responsive, some is caused by the 400 having more weight on the front wheel than Huskys of recent years have had. But the steering's sharpness is mostly a result of the quickest steering geometry (a claimed 28.5-degree steering head angle and 5.2 inches of trail, which is about 1.5 degrees and 0.5-inch less than on the 430WR) used on a stock Husqvarna in a long time.








The shape, construction and tuning of the exhaust pipe are faultless, but the pipe can toast your fingers when you fold out the long kickstart lever.



It also feels rather tall and unusual until you get used. The handlebar is low, which causes the rider to lean for somewhat; but once you get used to that position, you find it's part of the reason why the 400 carves around tight corne precisely. And the Husky feels taller than it actually is been the seat is padded with extremely hard foam that barely of the seat is padded.



By not following the contours of the exhaust pipe very closely, the left-side numberplate makes the 400 excess uncomfortably wide just above the footpegs.

After riding the bike, however, after experiencing how nimbly it flicks around sharp turns, how quickly it changes direction when threading through tight woods, how willingly it can be flopped over into a corner, we decided to measure the head angle and trail for ourselves, for the improvement in steering action seemed much more drastic than Husky's numbers would indicate. And sure enough, we found that the claimed steering angle is about right, but that the 400 actually has around 4.8 inches of trail, significantly less than what the company claims.

Whatever the numbers are, though, the 400WR certainly is the most nimble Husqvarna to come along in years. In some situations, in fact, it handles almost as quickly as, say, a Honda CR250R motocrosser, which is one of the most agile dirt machines to be found anywhere. And yet the 400 doesn't suffer any significant instability problems as a result of its quick steering. It's not quite as dead-stable, obviously, at high speeds as a 430WR or practically any other recent Husqvarna, but neither does it wiggle or twitch when trucking along at or near its 85-mph top speed.

If a rider prefers slightly slower steering, maybe for a desert

presses when sat upon. Neither does the firmness of the seanything to add to the 400's comfort level, although the biquite good in that respect, especially after the suspension properly set up.

Too bad we can't say as much about the 400WR's of brakes, which are all too typical of late-model Husqv brakes. The rear brake is adequate if not spectacular, bu front is marginal, especially for a double-leading-shoe Hauling the 400 down from speeds over 50 or 60 mph call an awful lot of lever pull; and when wet, both brakes go a altogether, and don't return until they've been dragged long, long time thereafter.

We also have little good to say about the 400WR's siler spark arrester, which is of the same design that Husqvarna been using for years—and that has been troublesome for julong. The arrester is comprised of a fine-wire screen and a with numerous small holes, all of which clogs up easily carbon and thus needs constant cleaning. We replaced the unit with an Answer Products silencer/arrester and elimin the problem without sacrificing anything in performance.

hat's nice to know. But it also brings us to a puzzling concluabout the 400WR: We like it. A lot. Enough to own one and it, in fact.

ou probably wouldn't have guessed that on your own, seeing ow we've registered so many complaints here about numerparts of the 400—its shocks, brakes, seat, spark arrester, berplate and, to a certain extent, front fork. Those all ld be legitimate complaints on any enduro bike, and they're t next to unacceptable on a \$3200 enduro bike.

xcept. Except that once the fixable problems of that group aken care of, the 400WR is a magnificent enduro machine, that ought to be able to elevate your trail-riding speed a h or two the first time you ride it. The bike is incredibly exceptionally nimble and uncommonly forgiving.

But it's also seriously flawed—although none of those flaws have anything to do with the engine, which is the best part of the entire motorcycle, despite being smaller than its predecessor. Still, we can't wholeheartedly recommend a bike with so many out-of-the-crate shortcomings to everyone interested in an Open-class enduro bike; we can't urge anyone to spend top dollar for a so-called "professional" competition bike knowing that they'll also have to invest considerable time and money to get it working properly. Nope, we can't do that. All we can say is that if you do choose to buy a 400WR and sort out its problems, you just might end up with the most enjoyable Open-class enduro bike you can buy.

Wait. Make that the most enjoyable enduro bike you can build.

## CIFICATIONS

ERA	_
Price	\$3195
rter	Husqvarna Motorcycle Co. Inc. 4925 Mercury St. San Diego, Calif. 92111
omer	service
е	(619) 565-1414

30 days

CLE )RLD }T: SQVARNA OWR

ENGINE/GEAR	BOX
Engine type	two-stroke Single
Bore x stroke	82.5 x 74mm
Displacement	396cc
Compression ra	tio 12.5:1
Claimed power	na
Claimed torque	na
Carburetion	38mm Mikuni
Ignition	CDI
Lubrication	premix
Primary drive	straight-cut gear
Gear ratios, ove	rall:1
6th	5.90
5th	7.00
4th	8.30
3rd	11.20
2nd	14.40
1st	20.80
Oil capacity	1 pt.
Starter	primary kick
Air filter	oiled foam

SUSPENSION	BRAKES/TIRES
Front Hu	sqvarna telescopio
Wheel travel	10.6 in.
Tube diamete	er 40mm
Rear	Ohlins dual shock
Wheel travel	. 11.8 in.
Brakes:	
Front	6.3 in. dual-
	leading shoe
Rear	6.3 in. drum
Tires:	
Front	3.00-21 Trelleborg
Rear	5.00-17 Trelleborg
Wheel:	
Front	1.60-21 aluminum
Rear	2.50-18 aluminum
CHASSIS	
Fuel capacity	2.8 gal.
Fuel tank mater	rial plastic
Swingarm mate	erial chrome-moly steel
Frame material	chrome-moly steel
Wheelbase	58.5 in.
Seat height	36.9 in.

Handlebar width	32.0 in.
Footpeg height	15.6 in.
Footpeg to seat top	21.8 in.
Footpeg to shift lever center	5.4 in.
Footpeg to brake lever center	4.9 in.
Swingarm length	20.8 in.
Swingarm pivot to drive sprocket center	3.2 in.
Gas tank filler hole	1.5 in.
Ground clearance	12.6 in.
Rake/trail (claimed)	28.5°/5.2 in.
Test weight w/half-tank fuel	259 lb
Weight distribution, front/rear, percent	48.3/51.7

